



18/001 - Norris Bros

1 Broughton Park
Old Lane North
Broughton
Skipton
North Yorkshire
BD23 3FD
+44 (0)1756 799 919
info@jbaconsulting.com

JBA
consulting



Groundwater Emergence Risk (JBA)

Site Boundary

 Tamworth Borough
Council Boundary

Groundwater levels

-  Less than 0.025m below
the ground surface
-  Between 0.025m and 0.5m
below the ground surface
-  Between 0.5m and 5m
below the ground surface
-  At least 5m below
the ground surface
-  No risk

Tamworth
Borough Council

Contains OS data © Crown copyright and
database right (2026). This document is the
property of Jeremy Benn Associates Ltd. It
shall not be reproduced in whole or in part,
nor disclosed to a third party, without the
permission of Jeremy Benn Associates Ltd.

www.jbaconsulting.com

B5493

Balfour





18/015 - Land off Gorsy Bank Road

1 Broughton Park
Old Lane North
Broughton
Skipton
North Yorkshire
BD23 3FD
+44 (0)1756 799 919
info@jbaconsulting.com

JBA
consulting



Groundwater Emergence Risk (JBA)

Site Boundary

 Tamworth Borough Council Boundary

Groundwater levels

-  Less than 0.025m below the ground surface
-  Between 0.025m and 0.5m below the ground surface
-  Between 0.5m and 5m below the ground surface
-  At least 5m below the ground surface
-  No risk

Tamworth
Borough Council

Contains OS data © Crown copyright and database right (2026). This document is the property of Jeremy Benn Associates Ltd. It shall not be reproduced in whole or in part, nor disclosed to a third party, without the permission of Jeremy Benn Associates Ltd.

www.jbaconsulting.com





18/025 - Former Wilnecote Youth Centre

1 Broughton Park
Old Lane North
Broughton
Skipton
North Yorkshire
BD23 3FD
+44 (0)1756 799 919
info@jbaconsulting.com

JBA
consulting



Groundwater Emergence Risk (JBA)

Site Boundary

 Tamworth Borough
Council Boundary

Groundwater levels

-  Less than 0.025m below the ground surface
-  Between 0.025m and 0.5m below the ground surface
-  Between 0.5m and 5m below the ground surface
-  At least 5m below the ground surface
-  No risk


Tamworth
Borough Council

Contains OS data © Crown copyright and database right (2026). This document is the property of Jeremy Benn Associates Ltd. It shall not be reproduced in whole or in part, nor disclosed to a third party, without the permission of Jeremy Benn Associates Ltd.

Greatare Close

Smithy Lane

New Road





20/090 - Land at Gorsey Bank Road

1 Broughton Park
Old Lane North
Broughton
Skipton
North Yorkshire
BD23 3FD
+44 (0)1756 799 919
info@jbaconsulting.com

JBA
consulting



Groundwater Emergence Risk (JBA)

Site Boundary

 Tamworth Borough Council Boundary


Groundwater levels

-  Less than 0.025m below the ground surface
-  Between 0.025m and 0.5m below the ground surface
-  Between 0.5m and 5m below the ground surface
-  At least 5m below the ground surface
-  No risk

Tamworth
Borough Council

Contains OS data © Crown copyright and database right (2026). This document is the property of Jeremy Benn Associates Ltd. It shall not be reproduced in whole or in part, nor disclosed to a third party, without the permission of Jeremy Benn Associates Ltd.

www.jbaconsulting.com





Halford Street

23/573 - Marmion House

1 Broughton Park
Old Lane North
Broughton
Skipton
North Yorkshire
BD23 3FD
+44 (0)1756 799 919
info@jbaconsulting.com

JBA
consulting



Groundwater Emergence Risk (JBA)

Site Boundary

 Tamworth Borough
Council Boundary

Groundwater levels

-  Less than 0.025m below
the ground surface
-  Between 0.025m and 0.5m
below the ground surface
-  Between 0.5m and 5m
below the ground surface
-  At least 5m below
the ground surface
-  No risk

Tamworth
Borough Council

Contains OS data © Crown copyright and
database right (2026). This document is the
property of Jeremy Benn Associates Ltd. It
shall not be reproduced in whole or in part,
nor disclosed to a third party, without the
permission of Jeremy Benn Associates Ltd.

www.jbaconsulting.com

0 30 60 m



B5493

Church Street

Silver Street